

SITRANS P200 Transmitters for pressure and absolute pressure for general applications Non-linearity: 0,25 percent (typically) wetted parts material:ceramics, stainless steel plus sealing material; non-wetted parts material: stainless steel Measuring range for gauge 0 to 150 psi, Overload- pressure 350 psi Output signal: 4 to 20 mA two-wire connection, power supply DC 7 to 33 V without explosion protection Electrical connection: plug to DIN EN 175301-803-A, thread for packed gland 1/2" - 14 NPT (with connector) Process connection: 1/2"-14 NPT female Sealing material between sensor and housing: Viton (FPM, Standard) Standard version

### Further information

**Industry Online Support (Manuals, Catalogs, Certificates, FAQ, ...)**

<https://support.industry.siemens.com/cs/products?mf=ps&lc=en-WW>

**Industry Mall (Online ordering system)**

<https://mall.industry.siemens.com>

