

PSEN ma adapter

380300



Adapter for connecting the sensor PSENma to PSS67 and PDP67.

Dane

Temperatura pracy:	-5 - 80 °C
Wtyczka ochronna 1:	IP68
wtyczka ochronna 2:	IP68