

SITRANS P220 Transmitters for pressure and absolute pressure fully welded version for high-pressure and refrigerant applications Non-linearity: 0,25 Percent (typically) wetted parts material: stainless steel; non-wetted parts material: stainless steel Measuring range for gauge: 0 to 100 bar, Overload- pressure 250 bar Output signal: 4 to 20 mA two-wire connection, power supply DC 7 to 33 V without explosion protection Electrical connection: Connection via mounted cable, 5m (not with explosion protection) Process connection: 1/2"-14 NPT male Standard version Standard version

## Further information

**Industry Online Support (Manuals, Catalogs, Certificates, FAQ, ...)**

<https://support.industry.siemens.com/cs/products?mfn=ps&lc=en-WW>

**Industry Mall (Online ordering system)**

<https://mall.industry.siemens.com>

