



## ZX-LDA41-N 2M

Smart Sensor amplifier and display, selectable voltage/current output, high/pass/low transistor PNP outputs

# Specifications

Output type	PNP
Sensing method	Amplifier
Material housing	PBT
Mounting method	DIN rail

## Downloads

CAD Library



**HOW TO GUIDE - Smart Sensor ZX-L Checking Width Measurement Guide**

EN PDF 1.19 MB



**Measurement Sensors Brochure**

EN PDF 1.29 MB



**ZX-L Brochure**

EN PDF 490 KB




**ZX-L (old amplifier version) Operation Manual**

EN PDF 4.45 MB



**ZX-L-N Users Manual**

EN PDF 3.08 MB



**ZX-L-N Smart Sensors (Laser Type) Datasheet**

EN PDF 1.04 MB

### TERMS OF WEBSITE USE

This PDF document was created from the European OMRON Industrial Automation website on 15 April, 2026. Click here for [terms of use](#).

**OMRON**

INDUSTRIAL AUTOMATION | INDUSTRIAL.OMRON.EU