



temperature sensors  
infrared sensor  
M18TUP14



- Connection via cable, 2 m
- D:S ratio 14:1
- Operating voltage 12...30 VDC
- Measuring range adjustable via teach-in
- Analog output 0...10 V
- PNP Alarm output switches at 10 V
- Temperature range 0 ... +300 °C

**Wiring diagram**




<b>Type code</b>	M18TUP14
Ident no.	3074921
<b>Operating mode</b>	infrared sensor
Ambient temperature	-20...+70 °C
Temperature range	≥0...≤300 °C
Switching point accuracy	± 0.5 °C
<b>Operating voltage</b>	12...30VDC
Short-circuit protection	yes/ cyclic
Reverse polarity protection	yes
Output function	NO contact, PNP/analog output
Voltage output	0...10V
Readiness delay	≤ 1.5 s
<b>Design</b>	cylindrical/threaded, M18T
Dimensions	86.5 mm
Housing material	stainless steel, V2A (1.4301)
Lens	semi-metal, Germanium
Connection	cable
Cable length	2 m
Cable cross section	5 x 0.5 mm <sup>2</sup>
Protection class	IP67
<b>Power-on indication</b>	LED green
Switching state	LED yellow

**Functional principle**



Temperature sensors are used in applications where temperatures for control and optimization of processes must be captured and monitored. The sensor operates only as a receiver. The thermal radiation of an object within a wave length range of 8 to 14 μm is transformed into an electrical signal via a thermopile and then further processed to become an output signal. Here the D:S (distance: spot) ratio is very important because it specifies the diameter of the spot at a defined distance. The sensor is optimally aligned, if the spot is completely covered by the object, whose temperature is to be monitored.

**D:S ratio**



temperature sensors  
infrared sensor  
M18TUP14

**Accessories**

Type code	Ident no.	Description	Dimension drawing
SMB18A	3033200	Mounting bracket, stainless steel, for sensors with 18 mm thread	 <p>Technical drawing of the SMB18A mounting bracket. Dimensions include: outer diameter <math>\varnothing 18,5</math>, inner diameter <math>\varnothing 4,6</math>, width 4,6, total height 41, mounting hole diameter 7,6, and a radius of <math>R 24,2</math>.</p>
SMB18SF	3052519	Mounting bracket, PTB black steel, for sensors with 18 mm thread	 <p>Technical drawing of the SMB18SF mounting bracket. Dimensions include: total height 50,8, mounting hole diameter 11,7, sensor bore diameter <math>\varnothing 5</math>, and a base width of 25,4.</p>
SMB18UR	3052517	Mounting bracket, for wall mounting, stainless steel 300, 2-piece, rotatable, 18 mm bore hole, screw set included	
LAT1812	3074262	Laser alignment aid, visible red, contains M12 laser emitter (laser class 2) and mounting bracket SMB1812, for sensors with 18 mm thread, 10 ... 30 VDC supply necessary	